



NFPA 96

Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations

2001 Edition

Reference: 8.2.1.1

Errata No.: 96-01-01

The Committee on Venting Systems for Cooking Appliances notes the following error in the 2001 edition of NFPA 96, *Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations*.

1. In section 8.2.1.1 revise to read as follows:

8.2.1.1 The air velocity through any duct shall be not less than 152.4 m/min (500 ft/min).

Issue Date: January 10, 2002