



# NFPA 96

## Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations

2001 Edition

**Reference: 8.2.1.1**

**Errata No.: 96-01-01**

The Committee on Venting Systems for Cooking Appliances notes the following error in the 2001 edition of NFPA 96, *Standard for Ventilation Control and Fire Protection of Commercial Cooking Operations*.

*1. In section 8.2.1.1 revise to read as follows:*

**8.2.1.1** The air velocity through any duct shall be not less than 152.4 m/min (500 ft/min).

**Issue Date: January 10, 2002**